

## CANADIAN SPORT PARACHUTING ASSOCIATION ASSOCIATION CANADIENNE DU PARACHUTISME SPORTIF TECHNICAL BULLETIN #114

## TECHNICAL BULLETIN # 114 6 January 2018

## Item #1 Aerodyne Service bulletin SB121817

Aerodyne has issued a service bulletin to address recent issues with their semi-stowless deployment bags.

**Actions to be taken:** To all packers, riggers and owners please review the service bulletin and ensure the deployment bag has the proper modification completed. Modifications can be identified by a red webbing stow pocket IAW SB 121817.

Robert MacNeill – Chair Technical and Safety Committee

OUR JOB, THEIR SAFETY, OUR AIM, PERFECTION.